

Aero Design Ltd.**Work Order Control Sheet**Work Order#: 2017-66 Date Opened: 12 April 2017 Title: AssemblyAircraft OEM: Eurocopter Aircraft Model: AS350 Product Type: Cargo Basket Product Model: XL Ski Quantity: 1**Work Order Contents**

Work Order/Build Sheets (Procedures Provided)
 Additional Work Sheets (Standard Practice)
 Drawings (See List Below)
 Parts Distribution Sheet
 Sub Component Tags
 Completed Certification
 Time Sheet (R&D)
 Notes

Initial or N/A

N/A
N/A
N/A
N/A
N/A
JC
N/A
N/A

Build Sheet Contents

Tasks Initialled
 Dual Inspections Initialled

Initial or N/A

N/A
N/A

Drawing List

Drawing #	Rev #	Description	Initial or N/A

Traveller

Initial or N/A

Component Completion

Quantity Complete on This Work Order
 Quantity Incomplete on This Work Order
 Further Processing Required Before Release
 Release to Stock as Components

As Instructed

1
N/A
N/A
N/A

Certification

Form One Completed
 Serviceable (Green) Tag Completed
 In Process (Yellow) Tag Completed
 Unserviceable (Red) Tag Completed
 Parts Placed in Stores for Distribution

Initial or N/A

N/A
JR
N/A
N/A
N/A

Additional Documentation

Documentation of a minor change
 Non-Conformance Report Required
 Service Difficulty Report Required

Initial or N/A

N/A
N/A
N/A

Billing

Local (Aero Design)
 Research and Development
 Third Party

Initial or N/A

JC
N/A
N/A

Notes:

Basket supplied dissassembled for re-powder coating.
 Basket was media blasted, re-powder coated, and returned to operator
 for re-assembly

Work performed by:

Print: J. Rekve

Sign: 

SCA: AD01

Date: 31-May-17

ICC / Dual Inspection performed by:

Print: N/A

Sign: SCA: Date:

Work Order closed by:

Print: J. Clarke

Sign: 

SCA: AD02

Date: 01-Jun-17

Approved Manufacturing Facility 73-04

Form 201003

Rev. Original 23 Sep 2014

BLACKCOMB HELICOPTERS LP.

AMO 133-95

1850 AIRPORT RD, PEMBERTON, BC, CANADA, V0N 2L0

NOMENCLATURE: QUICK RELEASE BASKETPART NO.: AS350 Series MAKE: Euro DesignSERIAL NO.: 94001-08REMOVAL REASON: Rehearsal / Paint☐ TO BE OVERHAULED☒ TO BE REPAIRED☐ TO BE SCRAPPEDTOTAL TIME: N/A TIME SINCE OVERHAUL: N/AWORK REPORT: FOQH 20 FEB 2017AIRCRAFT REMOVED FROM: C-FOQH
4535.6 A/F HOURS: 4535.6DATE: Feb 20/2017 INSPECTOR'S SIGNATURE: [Signature]

UNSERVICEABLE



1850 Airport Road
Pemberton, BC V0N 2L0
Canada
Phone: 604-894-5153
Fax: 604-938-1706
AMO: 133-95

Repair Order #1515

Date	Feb 20, 2017
Created By	Dan Wall
Type	Repair
Currency	CAD

Page 1 / 1

Repair Order #1515

To AERO DESIGN 9888A MALASPINA ROAD POWELL RIVER BC V8A 0G3 CANADA Tel: 604-483-2376, Fax: 604-483-2372 Email: jeff@aerodesign.ca	Order from Blackcomb Helicopters 1850 Airport Rd Pemberton, B.C. V0N 2L0 Tel: 604-894-5153, Fax: 604-938-1706
Ship to Blackcomb Helicopters - Pemberton 1850 Airport Road Pemberton, British Columbia, Canada V0N2L0 Tel: 604-894-5153, Fax: 604-938-1706	Bill to Blackcomb Helicopters - Main Office Suite 400, The Landing 375 Water Street Vancouver, BC V6B 5C6 Tel: 604-453-5050, Fax: 604-453-5051

** Work to be accomplished at this time **

Please, perform Repair
A work report is required
Estimation is needed.

Parts description

Part Number	Description	Tracking #	Ser/Batch #	TTSN	TTSO	Reg	Est. Cost
94010-01	CARGO BASKET, LOWER	28505	94001-08				\$2225.00
C.C	Defect	REPLACE DAMAGED WEBBING, SAND BLAST, AND POWDER COAT.					

NOTE:(1) As per CARs Part V Standard 571 Appendix J, please provide the information below: A) If applicable Airworthiness Directives exist or were complied with, please include the information on the component history record, release certificate, or other supporting documentation clearly indicating compliance status. B) If no applicable Airworthiness Directives exist, please enter NONE in Block 12 of the release certificate. Sign below and return to (The above named Company Division) I, _____ (approved signature) verify that any parts on PO/RO# _____ have no applicable Airworthiness Directives on _____ (date). (2) All aeronautical products must be repaired and overhauled in accordance with the current manufacturers approved manuals unless otherwise specified on this Purchase Order.

All Service Difficulties discovered during the work described must be reported back to Blackcomb Helicopters LP


Signature

February 20, 2017

Date

AERO Design Ltd.

Quote

9888A Malaspina Road
Powell River, BC, V8A 0G3
Phone: 604-483-AERO (2376)
Fax: 604-483-2372

Date	20-Feb-17
------	-----------

Customer:
Name: Blackcomb Helicopters
Address: 1850 Airport Road Pemberton, BC, V0N 2L0
Phone: 604-894-5153
Fax:
Attention: Mat Melsness
Currency: CAD

Ship To:
Name:
Address:
Phone:
Fax:
Attention:

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
1	Repairs to Cargo Basket Assembly 94010-01 Labour - Remove hardware/hinge (supplied disassembled)	0	125.00	0.00
2	Labour - Cut mesh off end, clean up for welding	2	125.00	250.00
3	Labour - weld new mesh on end, repairs	2	125.00	250.00
4	Labour - media blast, prep for powder coat	3	125.00	375.00
5	Powder coat	1	300.00	300.00
	Optional			
6	Handle Brackets 84267-01	2	100.00	200.00
7	Lid Prop 36280-01	1	130.00	130.00
8	Hinge MS20001P4-9600	1	220.00	220.00
9	Hardware (not including hinge rivets)	1	50.00	50.00
10	Handle Assembly 84261-01	1	200.00	200.00
11	Labour - Assemble basket	2	125.00	250.00
	Notes 1. Quote is valid for 30 days 2. Price is quoted FOB Powell River, shipping, duties, brokerage, taxes are not included. 4. Cheque, wire/e-transfer, Visa/Mastercard accepted. 5. Prevailing interest will be charged on all overdue accounts.			
		Subtotal	CAD	2,225.00
		PST	7.00%	155.75
		GST	5.00%	111.25
		Total	CAD	\$2,492.00

Ship to:

AERO DESIGN

9888A Malaspina Road
Powell River, BC V8A 0G3
(604) 483-2376

From:

Blackcomb Helicopters

1850 Airport Road
Pemberton, BC, Canada
V0N 2L0
(604) 894-5153

BLACKCOMB HELICOPTERS LP.

AMO 133-95

1850 AIRPORT RD, PEMBERTON, BC, CANADA, V0N 2L0

NOMENCLATURE: Quick Release BasketPART NO.: AS350 Series MAKE: AeroSERIAL NO.: 94001-08REMOVAL REASON: Refinish / Paint☐ TO BE OVERHAULED☒ TO BE REPAIRED☐ TO BE SCRAPPEDTOTAL TIME: N/A TIME SINCE OVERHAUL: N/AWORK REPORT: EQQH 20 FEB 2017AIRCRAFT REMOVED FROM: C-EQQH A/F HOURS: 4536.6DATE: Feb 20 / 2017 INSPECTOR'S SIGNATURE: [Signature]

UNSERVICEABLE



1850 Airport Road
Pemberton, BC V0N 2L0
Canada
Phone: 604-894-5153
Fax: 604-938-1706
AMO: 133-95

Repair Order #1515	
Date	Feb 20, 2017
Created By	Dan Wall
Type	Repair
Currency	CAD
Page 1 / 1	

Repair Order #1515

To AERO DESIGN 9888A MALASPINA ROAD POWELL RIVER BC V8A 0G3 CANADA Tel: 604-483-2376, Fax: 604-483-2372 Email: jeff@aerodesign.ca	Order from Blackcomb Helicopters 1850 Airport Rd Pemberton, B.C. V0N 2L0 Tel: 604-894-5153, Fax: 604-938-1706
Ship to Blackcomb Helicopters - Pemberton 1850 Airport Road Pemberton, British Columbia, Canada V0N2L0 Tel: 604-894-5153, Fax: 604-938-1706	Bill to Blackcomb Helicopters - Main Office Suite 400, The Landing 375 Water Street Vancouver, BC V6B 5C6 Tel: 604-453-5050, Fax: 604-453-5051

** Work to be accomplished at this time **

Please, perform Repair
A work report is required
Estimation is needed.

Parts description

Part Number	Description	Tracking #	Ser/Batch #	TTSN	TTSO	Reg	Est. Cost
94010-01	CARGO BASKET, LOWER	28505	94001-08				\$2225.00
C.C.	Defect	REPLACE DAMAGED WEBBING, SAND BLAST, AND POWDER COAT.					

NOTE:(1) As per CARs Part V Standard 571 Appendix J, please provide the information below: A) If applicable Airworthiness Directives exist or were complied with, please include the information on the component history record, release certificate, or other supporting documentation clearly indicating compliance status. B) If no applicable Airworthiness Directives exist, please enter NONE in Block 12 of the release certificate. Sign below and return to (The above named Company Division) I, _____ (approved signature) verify that any parts on PO/RO# _____ have no applicable Airworthiness Directives on _____ (date). (2) All aeronautical products must be repaired and overhauled in accordance with the current manufacturers approved manuals unless otherwise specified on this Purchase Order.

All Service Difficulties discovered during the work described must be reported back to Blackcomb Helicopters LP


Signature

February 20, 2017

Date

AERO Design Ltd.

9888A Malaspina Road

Powell River, BC, V8A 0G3

Phone: 604-483-AERO (2376)

Fax: 604-483-2372

Quote

Date	20-Feb-17
------	-----------

Customer:

Name: Blackcomb Helicopters
 Address: 1850 Airport Road
 Pemberton, BC, V0N 2L0
 Phone: 604-894-5153
 Fax:
 Attention: Mat Melsness
 Currency: CAD

Ship To:

Name:
 Address:

 Phone:
 Fax:
 Attention:

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
1	Repairs to Cargo Basket Assembly 94010-01 Labour - Remove hardware/hinge (supplied disassembled)	0	125.00	0.00
2	Labour - Cut mesh off end, clean up for welding	2	125.00	250.00
3	Labour - weld new mesh on end, repairs	2	125.00	250.00
4	Labour - media blast, prep for powder coat	3	125.00	375.00
5	Powder coat	1	300.00	300.00
	Optional			
6	Handle Brackets 84267-01	2	100.00	200.00
7	Lid Prop 36280-01	1	130.00	130.00
8	Hinge MS20001P4-9600	1	220.00	220.00
9	Hardware (not including hinge rivets)	1	50.00	50.00
10	Handle Assembly 84261-01	1	200.00	200.00
11	Labour - Assemble basket	2	125.00	250.00
	Notes 1. Quote is valid for 30 days 2. Price is quoted FOB Powell River, shipping, duties, brokerage, taxes are not included. 4. Cheque, wire/e-transfer, Visa/Mastercard accepted. 5. Prevailing interest will be charged on all overdue accounts.			
		Subtotal	CAD	2,225.00
		PST	7.00%	155.75
		GST	5.00%	111.25
		Total	CAD	\$2,492.00

**Aero Design Ltd.**

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Nomenclature: BASKET LID (AS350 XL) No. of pieces: 1Manufacturer: AERO DESIGN LTD.Part No.: 94012-01 Serial/Batch No.: NSNTTSN: N/A TSO: N/A Rem.: N/AWork Order No.: 2017-66Remaining Tasks to be Performed: ASSEMBLY w/ BODYSignature: [Signature] ADDate: 31 May 17 Lic. No. / SCA 73-04

Form# 20.E.02

Rev. 1 24 April 2014

Serviceable

**Aero Design Ltd.**

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Nomenclature: BASKET BODY (AS350 XL) No. of pieces: 1Manufacturer: AERO DESIGN LTD.Part No.: 94011-01 Serial/Batch No.: NSNTTSN: N/A TSO: N/A Rem.: N/AWork Order No.: 2017-66Remaining Tasks to be Performed: ASSEMBLY w/ LIDSignature: [Signature] ADDate: 31 May 17 Lic. No. / SCA 73-04

Form# 20.E.02

Rev. 1 24 April 2014

Serviceable



Aero Design Ltd.

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Serviceable

Remarks



Aero Design Ltd.

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Serviceable

Remarks
